



SINGLE PHASE SNAP-ACTING MOTOR PROTECTORS

Overcurrent, overtemperature and excessive locked rotor protection


TYPE F




TYPE FPM PANEL MOUNT
SOLDER LUGS
MANUAL RESET




TYPE FPA PANEL MOUNT
SOLDER LUGS
AUTO-RESET




TYPE FPM PANEL MOUNT
QUICK CONNECT
MANUAL RESET




TYPE FPA PANEL MOUNT
QUICK CONNECT
AUTO-RESET




TYPE FA FLUSH MOUNT
SOLDER LUGS
AUTO-RESET



TYPE FM FLUSH MOUNT
SOLDER LUGS
MANUAL RESET



TYPE FA FLUSH MOUNT
QUICK CONNECT
AUTO-RESET



TYPE FM FLUSH MOUNT
SOLDER LUGS
MANUAL RESET